EPA Region 5 Records Ctr. 371870

2300 North Broadway • P.O. Box 2233 • Decatur, Illinois 62526 • 217/877-2100

September 14, 1983

HAROLD S. SHAFFER, PE-SE ROBERT G. KRIMMEL, PE-LS VAN A. SILVER, PE

7386

Mr. Lawrence W. Eastep, P.E., Manager Permit Section Division of Land Pollution Control Illinois Environmental Protection Agency 2200 Churchill Road Springfield, Illinois 62706

RE: 1.1530408 - MACON COUNTY

DECATUR/MACON COUNTY LANDFILL

PERMIT NO. 1976-4-0P

RECEIVED

SEP 15 1983

E.P.A. — D.L.P.C. STATE OF ILLINOIS

Dear Mr. Eastep:

This letter is to confirm our meeting yesterday concerning the ground watering monitoring system at the referenced landfill. Present at that meeting were Rob Watson and John Student of your agency, J. W. Spawr and Don Williams of Macon County Landfill Board of Director and the undersigned. After much discussion, it was decided that a first step would be clean the existing downgradient wells in an attempt to provide a satisfactory system. Along with this, our office will research our files and resubmit well installation data for your review and also attempt to obtain more data concerning the exact location and depth of the water supply well currently being used at the upgradient well.

If this does not provide a satisfactory system, we will then submit an upgraded system for your review.

Very truly yours,

SHAFFER, KRIMMEL, SILVER & ASSOCIATES, INC.

BY:

Robert G. Krimmel

RGK/ndb

cc: Mr. Don Williams

Macon County Landfill

CIVIL ENGINEERS

**GEOTECHNICAL ENGINEERS** 

STRUCTURAL ENGINEERS

LAND SURVEYORS . CONSTRUCTION OHALITY CONTROL